

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 7,314,537
APPLICATION NO.: 10/674,920
ISSUE DATE : January 1, 2008
INVENTOR(S) : Craig T. Baldwin et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 1, line 54, "particularly, to an apparatus" should read --particularly, an apparatus--.

In column 3, line 14, "of the two signals are" should read --of the two signals is--.

In column 3, line 45, "system 100 can comprises a batch" should read --system 100 can comprise a batch--.

In column 5, line 64, "system 200 can comprises a batch" should read --system 200 can comprise a batch--.

In column 13, line 38, "106.25-826.3" should read --106.25=826.3--.

In column 13, line 43, "Toko Electronics" should read --Tokyo Electronics--.

In the Drawings, Fig. 7, at box 750, "INTERMODLATION" should read --INTERMODULATION--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Wood, Herron & Evans, L.L.P.
441 Vine St., Suite 2700
Cincinnati, OH 45202

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. **SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No.: 7,314,537
Issue Date: January 1, 2008
Serial No.: 10/674,920
Applicant: Craig T. Baldwin et al.
Title: METHOD AND APPARATUS FOR DETECTING A PLASMA
Attorney Docket: TAZ-256
Confirmation No.: 2601

Cincinnati, Ohio 45202

Electronically Filed

March 17, 2009

Certificate of Corrections Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION
(37 CFR §§ 1.322(a), 1.323)

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. The patent contains errors that occurred through the fault of the U.S. Patent and Trademark Office. The patent also contains an error that occurred by Applicant in the specification.

Form PTO/SB/44 outlining the corrections to be made is submitted herewith.

Applicants submit the required fee of \$100 for this request. If any deficiencies or credits are necessary to complete this communication, please apply them to Deposit Account No. 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

By: / Joseph R. Jordan /
Joseph R. Jordan, Reg. No. 25,686

2700 Carew Tower
441 Vine Street
Cincinnati, OH 45202
(513) 241-2324 (telephone)
(513) 241-6234 (facsimile)